



103 Kisco Avenue, Mount Kisco (C002)

Legend

- Radon Sample Location
- Exterior Wall
- Interior Wall
- Entry door
- OF - Office
- BR - Bathroom
- EC - Electrical Closet
- RL - Reception/Lobby
- LG - Lounge
- ST - Storage Trailer



Weston Solutions, Inc.

In Association with Scientific and Environmental Associates, Inc.,
Environmental Consultants, Inc., Avatar Environmental, LLC,
On-Site Environmental, Inc. and Sovereign Consulting, Inc.

Figure 6B:
C002 Radon Analytical Results Map

Canadian Radium and Uranium Site
Mount. Kisco, New York

U.S. ENVIRONMENTAL PROTECTION AGENCY
Removal Support Team 3
CONTRACT # EP-S2-13-01

Notes:

Radon sampling was conducted using charcoal canisters
Radon analytical results are reported in pico curies per liter (pCi/L)

EPA OSC:	E. DALY
RST SPM:	B. NWOSU
PROJECT #:	30400.021.006.2053